Some Commutation Phenomena Of Direct Current Machinery

F. C. Clark


1905

537.83 C 54


ARMOUR INST. OF TECH. LIB.



AT 5 Clark, F.C.
Some commutation phenomena
of direct current machinery







SOME COMMUTATION PHENOMENA

of

DIRECT CURRENT MACHINERY.

Being a thesis presented

F.C. Clark.

for the degree

of

Bachelor of Science in Electrical Engineering,
Having completed the prescribed course in

Electrical Engineering

at

ILLINOIS INSTITUTE OF TECHNOLOGY PAUL V. GALVIN LIBRARY 35 WEST 33RD STREET CHICAGO, IL 60616

ARMOUR INSTITUTE OF TECHNOLOGY.

June first one thousand nine hundred and five.

J. M. Raymond

L. M. Raymond

Lean of Engineering Studies

Le. Morrison

Stari of Cultural Studies

v

C54

Current Commutation.

Much attention has been given to the theory of commutation in direct current machinery but few attempts to measure the current flowing in the coil that, during commutation, is short-circuited are on record.

An attempt will be made in this paper to throw a little light on the subject of this measurment, and on the factors governing the magnitude and the law of variation of this current under different give conditions. The first, in importance, of these factors is that of contact resistance. By the term contact resistance is understood the resistance of the contact between the surface of the commutator and that of the brush. This contact resistance is the main factor in determining whether or not the current during short-circuit will or willnot be excessive in magnitude, and, in general has no bearing on the rate of change of the current.

The rate of change or shape of the wave of this current will depend on the self induction of the coil, the frequency of commutation and upon the electromotive forces induced in it at the different stages of commutation.

As this wave form is, at present, of secondary importance to the magnitude of the current I will first take up the questions of contact resistance.


For the purpose of determining this resistance under various 17973

conditions a commutator was mounted on a shaft running in bearings and equipped with a belt and pulley wheel. To remove all inductive effects this commutator was mounted without an armature and to secure the passage of a current from one segment to another, or others as the case may be, a brass ring was soldered to one end making good contact with each segment. This commutator was run by a variable speed motor and the resistance determined by the fall of potential method which required the following apparatus:-

- 1 Weston portable voltmeter (0 ÷ 5)
- 1 Weston portable ammeter (0 50)
- 1 Tachometer.
- I Lamp rack and source of supply current.
 The apparatus was connected as shown in the scheme on the
 following page. The brushes used were of carbon in all cases,
 three grades being used and designated as follows:-
 - No. 1 Of medium fine grain and medium hardness
 - " 2 " " harder than No. 1.
 - " 3 " extemely fine grain and very soft.

Brushes Nos..1 and 2 were such as are met with in American current practice. No. 3 was of French manufacture and was more of a graphite composition than of ordinary carbon. The conductivity of No. 3 was almost four times as great as that





Same of calling Plants



of Nos. 1 and 2, which were nearly equal.

The tests made on these brushes were to determine the relation of their contact resistance to the following conditions or qualities:-

- 1. Speed.
- 2. Temperature.
- 3. Current density.

A determination of their coefficient of friction was also made.

To determine the relation between the contact resistance and speed a series of runs were made in which a constant current-density was maintained in the brushes and the speed varied. At each variation of the speed readings were made on the tachometer, voltmeter and ammeter. The temperature in this case was kept as nearly constant as possible by running the commutator, before any reading was made, until the temperature ceased to rise. At various speeds varied amounts of heat were generated but owing to the slight amount of increase due to this no appreciable error was introduced.

The temperature effect of contact resistance was unsatisfactory from all points of view. The commutator was so large
in proportion to the amount of heat generated in that its temperature was but slightly affected and external heating was
resorted to. This was accomplished by means of incandescent



lights were placed under and within two inches of the commutator. This series of runs was made at constant speed and
current and when the voltmeter showed an appreciably drop over
the brushes and commutator readings of speed, current and potential drop were made and the commutator stopped. The temperature was taken by means of a thermometer placed on the surface
of the commutator and covered with waste.

The third set of runs, made at constant speed with variable current density, were made by running the commutator at a given speed with maximum current until a constant temperature had been reached, then the current was reduced and readings immediately taken on all instruments. With this precaution I believe that temperature errors were practically eliminated. After each set of readings the current was raised to full value and allowed to remain there three minutes before it was again reduced in order to obtain readings.

The brush rigging was mounted so that it could be free to rotate, in order to obtain the coefficient of friction. The method of doing this was to balance the torque, exerted on it by the brushes, by a spring balance. Readings were made for various brush tensions and commutator speeds.

The brush tension in all the following data was one and a half pounds per square inch except in cases where noted. This




brush tension was obtained by means of a spring balance.

The curves for any set of data are on the page or pages immediately following it. When two sets of data occur on one page the first curve met with will be plotted from the first set of data on that page.


Before each run care was taken to see that the brush was fitted to the surface of the commutator. In cases where the brush did not bear all over its surface it was ground to the contour of the commutator in the usual manner with fine sand-paper and the marks of the sand-paper removed by running the commutator for some time before the readings were started. The surface of the commutator was smooth and well polished in all cases.

| Tach. | R.P.M. 0 | E. 0/60 | I. 12. | R. 0.05 | R/a" .004 |
|------------|-------------|------------|-----------|------------|-----------|
| 59 | 720 | 0.75 | 18 | 0.06 | .048 |
| 64 | 780 | 1.20 | 10 | 0.10 | .08 |
| 72 | 880 | 1.80 | 11 | 0.15 | .120 |
| 76 | 932 | 2. 20 | 17 | 0.19 | .144 |
| 85 | 1040 | 2.80 | 69 | 0.23 | .184 |
| 100 | 1208 | 3.10 | 11 | 0.25 | . 200 |
| 109 | 1315 | 3.70 | 19 | 0.30 | . 240 |
| 118 | 1422 | 3.90 | | 0.32 | . 256 |
| 131 | 1608 | 4.10 | 11 | 0.34 | . 272 |
| | | #2. | | | |
| 0 | 0 | 0.25 | 12.5 | 0.02 | .016 |
| 60 | 728 | 1.00 | 12.0 | 0.08 | .064 |
| 65 | 792 | 1.20 | 19 | 0.10 | .08 |
| 69.5 | 850 | 1.30 | et . | 0.11 | .088 |
| 75 | 920 | 1.50 | n | 0.125 | .100 |
| 85 | 1040 | 1.60 | 19 | 0.133 | .1064 |
| 90 | 1087 | 2.30 | 11 | 0.192 | .1536 |
| Q 8 | 1183 | 2.50 | 11 | 0.208 | .1664 |
| 104 | 1256 | 2.65 | 11 | 0.220 | .1760 |
| 110 | 1328 | 3.10 | 17 | 0.250 | .2000 |
| 118 | 1454 | 3.20 | eŦ | 0/268 | . 2144 |
| 123 | 1516 | 3.60 | 11 | 0.3000 | . 2400 |
| 128 | 1576 | 4.20 | 17 | 0.350 | . 2800 |












| Tach. | қ. Р. И. | 1 | I. | R. | R/=" |
|-------|----------|--------------|------|-------|--------|
| 0. | 0. | 0.32 | 12.0 | 0.025 | 01020 |
| 60. | 728. | 0.70 | 41 | 0.058 | 0.0464 |
| 67. | 820. | 1.00 | 41 | 0.083 | 0.0664 |
| 72. | 880. | 1.10 | 40 | 0.091 | 0.0728 |
| 78. | 960. | 1.30 | ** | 0.108 | 0.0864 |
| 84. | 1012. | 1.50 | 17 | 0.125 | 0.1000 |
| 92. | 1126 | 2.10 | 11 | 0.176 | 0.1408 |
| 100. | 1 208. | 2.60 | 17 | 0.217 | 0.1736 |
| 105. | 1280. | 2.75 | 19 | 0.229 | 0.1832 |
| 120. | 1480. | 3.50 | 11 | 0.291 | 0.2328 |
| 128. | 1564. | 5. 60 | 19 | 0.330 | 0.2640 |
| | | | | | |


#4.

| Ι. | RI. | т. | R.P.M. | Time. | R. | R/ ". |
|------|-------|-----|--------|-------|-------|--------|
| 10.5 | 3. 30 | 26. | 1000. | 10:34 | 0.314 | 0.2512 |
| ** | 3.00 | 29. | 17 | : 37 | 01285 | 0.2080 |
| ** | 2, 25 | 31. | 1012. | :40 | 0.214 | 0.1712 |
| 19 | 1.60 | 35. | 17 | :48 | 0/145 | 0.1160 |
| 10.0 | 1.37 | 36. | 17 | 11:07 | 0.137 | 0.1096 |
| 10.5 | 1.30 | 41. | ü | :20 | 0.123 | 0.0984 |
| 10.0 | 1.00 | 44. | ** | :40 | 0.100 | 0.0800 |












| ,,D. |
|------|
|------|

| I. | RI. | r. | R.P.M. | R. | R/ ". |
|--------|--------------|-----------------|--------|--------|--------|
| 1.00 | 0.45 | 42. | 1000. | 0.45 | 0.3600 |
| 3, 25 | 1.00 | 10 | 19 | 0.307 | 0.2456 |
| 5.50 | 1.30 | 11 | 11 | 0.236 | 0.1888 |
| 7.50 | 1.45 | ** | a a | 0.253 | 0.2024 |
| 10.00 | 1.60 | " | 11 | 0.160 | 0.1280 |
| 12.25 | 1.75 | ** | ** | 0.142 | 0.1136 |
| 15.50 | 1.90 | 11 | 2 | 0.116 | 0.0928 |
| 18.50 | 2.10 | 11 | 11 | 0.113 | 0.0914 |
| 20.50 | 2.20 | 11 | 10 | 0.110 | 0.0880 |
| 23.50 | 2.45 | 10 | 19 | 0.104 | 0.0832 |
| 26.00 | 2.40 | ** | 11 | 0.0919 | 0.0736 |
| 27.50 | 2.50 | 48 | 17 | 0.0909 | 0.0727 |
| | | _# 6. | | | |
| 2.50 | 1.10 | 39. | 1000. | 0.440 | 0.352 |
| 5.50 | 1.00 | 18 | 11 | 0.290 | 0.232 |
| 7.50 | 1.90 | - 51 | 11 | 0.216 | 0.1728 |
| 10.00 | 1.90 | 10 | n | 0/190 | 0.1520 |
| 13.00 | 2.00 | 18 | п | 0.153 | 0.1224 |
| 16.50 | 2.25 | d. | ** | 0.136 | 0.1088 |
| 19.25 | 2.35 | 18 | tf. | 0/122 | 0.0976 |
| 23.00 | 2.50 | 19 | ** | 0.109 | 0.0872 |
| 25, 25 | 2.60 | 11 | 17 | 0.102 | 0.0760 |
| 27.50 | 2.60 2.80 | 44 | 11 | 0/095 | 0.0760 |
| 30.50 | 2.75 | ı | t) | 0.0910 | 0.0728 |
| | | | | | |









| I. | RI. | S. | R. | R/ ". |
|-------|-------|-------|---------|---------|
| 1.00 | U.75 | 860. | 0.7500 | 0.60000 |
| 2.25 | 1.00 | ii. | 0.4500 | 0.36000 |
| 5.00 | 1.35 | 10 | 0.27000 | 0.21600 |
| 7.00 | 1.50 | 10 | 0.2100 | 0.16800 |
| 11.50 | 1.60 | 19 | 0.1300 | 0.10400 |
| 16.50 | 1.75 | 19 | 0.1060 | 0.08480 |
| 22.00 | 2.00 | 17 | 0.0909 | 0.07272 |
| 26.75 | 2. 20 | 00 | 0.0820 | 0.06560 |
| | | | #8• | |
| 12.5 | 1.75 | 720. | 0.140 | 0.1120 |
| 10 | 1.70 | 900. | 0.130 | 0.1040 |
| 66 | 1385 | 990. | 0.148 | 0.1184 |
| 10 | 1.95 | 1060. | 0.1560 | 0.1248 |
| +9 | 2.00 | 1115. | 0.160 | 0.1280 |
| 9.0 | 2.25 | 1197. | 0.180 | 0.1440 |
| 10 | 2,90. | 1260. | 0.232 | 0.1856 |
| 94 | 3,60 | 1330. | 0.288 | 0.2304 |
| ** | 4.25 | 1395. | 0.344 | 0.2752 |
| 19 | 5, 25 | 1460 | 0.420 | 0.3360 |
| eV | 6.20 | 1520 | 0.490 | 0.3920 |
| 48 | 7.10 | 1590. | 0.560 | 0.4480 |













| I. | RI. | S. | R. | R/ ". |
|--|--------------------------------------|----------------------|--|--|
| 3.5 | 1.00 | 1000. | 0.234 | 0.1872 |
| 6.5 | 1.40 | 41 | 0.215 | 0.1720 |
| 7.0 | 1.25 | d | 0.178 | 0.1404 |
| 10.5 | 1.70 | rt | 0.161 | 0.1288 |
| 13.5 | 1.50 | a) | 0.111 | 0.0888 |
| 19.5 | 1.75 | u | 0.090 | 0.0720 |
| 26.5 | 2.00 | 11 | 0.0754 | 0.06032 |
| 31.0 | 2. 20 | d | 0.0709 | 0.05672 |
| | | | | |
| | | | #10. | |
| 3. 25 | 1.50 | 1130. | #10. 0.460 | 0.3680 |
| 3. 25 8. 65 | 1.50 2.00 | 1130. | | 0.3680 |
| | | | 0.460 | |
| 8.65 | 2.00 | 45 | 0.460 | 0.1848 |
| 8.65 10.75 | 2.00 | ef e) | 0.460 0.231 0.196 | 0.1848 0.1568 |
| 8.65 10.75 13.50 | 2.00 2.10 2.40 | s) s) | 0.460 0.231 0.196 0.177 | 0.1848 0.1568 0.1416 |
| 8.65 10.75 13.50 19.00 | 2.00 2.10 2.40 2.50 | 11 11 | 0.460 0.231 0.196 0.177 0.131 | 0.1848 0.1568 0.1416 0.1048 |
| 8.65 10.75 13.50 19.00 27.00 | 2.00 2.10 2.40 2.50 2.80 | 11 12 13 14 | 0.460 0.231 0.196 0.177 0.131 0.103 | 0.1848 0.1568 0.1416 0.1048 0/8240 |













#11.

| Ι. | RI. | R.P.M. | R. | R/ ". |
|--|--------------------------------------|------------------------|--|---|
| 5.75 | 1.65 | 1130. | 0.280 | 0.2240 |
| 7.2 | 2.15 | 58 | 0.300 | 0.2400 |
| 9.00 | 1.90 | 19 | 0.210 | 0.1680 |
| 11.60 | 2, 25 | 10 | 0.194 | 0.1552 |
| 14.50 | 2.30 | 18 | 0.150 | 0.1200 |
| 16.75 | 2.65 | 10 | 0.164 | 0.1412 |
| 21.50 | 2.70 | H | 0.125 | 0.1000 |
| 28.50 | 2.90 | , 19 | 0.101 | 0.0808 |
| 31.40 | 3.00 | 11 | 0.0955 | 0.0764 |
| | | | | |
| | | #1 | 2. | |
| I. | RI. | #1 R.P.M. | 2. R. | R/ ". |
| I. 5.75 | RI. | | | |
| | | R.P.M. | R. | |
| 5.75 | 1.05 | R.P.M. 1265. | R. 0.128 | 0.1456 |
| 5.75 9.60 | 1.05 | R.P.M. 1265. | R. 0.128 0.145 | 0.1456 0.1160 |
| 5.75 9.60 10.75 | 1.05 1.40 2.30 | R.P.M. 1265. | R. 0.128 0.145 0.215 | 0.1456 0.1160 0.1720 |
| 5.75 9.60 10.75 13.50 | 1.05 1.40 2.30 2.65 | R.P.M. 1265. | R. 0.128 0.145 0.215 0.196 | 0.1456 0.1160 0.1720 0.1568 |
| 5.75 9.60 10.75 13.50 16.00 | 1.05 1.40 2.30 2.65 2.80 | R.P.M. 1265. | R. 0.128 0.145 0.215 0.196 0.175 | 0.1456 0.1160 0.1720 0.1568 .0.1200 |
| 5.75 9.60 10.75 13.50 16.00 20.75 | 1.05 1.40 2.30 2.65 2.80 2.95 | R. P.M. 1265. "" "" "" | R. 0.128 0.145 0.215 0.196 0.175 0.142 | 0.1456 0.1160 0.1720 0.1568 .0.1200 0.1136 |














| I. | RI. | R.P.M. | R. | R/ ". |
|--|--|--|--|--|
| 3,60 | 2.10 | 1330. | 0.600 | 0.4800 |
| 5.50 | 2. 25 | 00 | 0.409 | 0.3672 |
| 8. 25 | 2.70 | 16 | 0.320 | 0.2560 |
| 9.00 | 2.90 | st | 0.322 | 0.2576 |
| 11.75 | 3.10 | 66 | 0.264 | 0.2312 |
| 16.75 | 3.20 | 11 | 0.199n | 0.1592 |
| 22.50 | 3. 50 | # | 0.146 | 0.1168 |
| 26.70 | 3. 48 | 17 | 0.130 | 0.1040 |
| 30.75 | 3.65 | 19 | 0.115 | 0.0920 |
| | | #1 | Λ | |
| | | // - | T. | |
| I. | RI. | R.P.M. | R. | R/ ". |
| I. 3. 20 | RI. 2.40 | | | R/ ". |
| | | R.P.M. | R. | |
| 3. 20 | 2.40 | R.P.M. 1400. | R. 0.750 | 0.6000 |
| 3. 20 7. 25 | 2.40 2.90 | R.P.M. 1400. | R. 0.750 0.400 | 0.6000 0.3200 |
| 3. 20 7. 25 9. 50 | 2.40 2.90 3.15 | R.P.M. 1400. | R. 0.750 0.400 0.331 | 0.6000 0.3200 0.2648 |
| 3. 20 7. 25 9. 50 13. 75 | 2.40 2.90 3.15 3.40 | R.P.M. 1400. | R. 0.750 0.400 0.331 0.248 | 0.6000 0.3200 0.2648 0.1984 |
| 3.20 7.25 9.50 13.75 18.50 | 2.40 2.90 3.15 3.40 3.65 | R.P.M. 1400. | R. 0.750 0.400 0.331 0.248 0.197 | 0.6000 0.3200 0.2648 0.1984 0.1576 |
| 3.20 7.25 9.50 13.75 18.50 19.00 | 2.40 2.90 3.15 3.40 3.65 3.65 | R.P.M. 1400. | R. 0.750 0.400 0.331 0.248 0.197 0.192 | 0.6000 0.3200 0.2648 0.1984 0.1576 0.1536 |
| 3.20 7.25 9.50 13.75 18.50 19.00 23.00 | 2.40 2.90 3.15 3.40 3.65 3.65 3.70 | R.P.M. 1400. """"""""""""""""""""""""""""""""""" | R. 0.750 0.400 0.331 0.248 0.197 0.192 0.169 | 0.6000 0.3200 0.2648 0.1984 0.1576 0.1536 0.1352 |












| I. | RI. | R.P.M. | R. | R/ ". |
|-------|------|--------|-------|--------|
| 5.50 | 3.0 | 1460. | 0.540 | 0.4320 |
| 7. 25 | 3.1 | 10 | 0.427 | 0.3516 |
| 9.00 | 3.3 | и | 0.366 | 0.2328 |
| 14.00 | 3.5 | *P | 0.250 | 0.2000 |
| 19.00 | 3.5 | 11 | 0.131 | 0.1048 |
| 23.00 | 3.65 | n | 0.159 | 0.1273 |
| 27.00 | 3.80 | " | 0.140 | 0.1120 |
| 30.00 | 3.80 | el | 0.126 | 0.1008 |
| | | | | |

#16.

| 1. | A1. | R.PM. | R. | R/ ". |
|-------|-------|-------|-------|--------|
| 4.25 | 3. 20 | 1530. | 0.727 | 0.5816 |
| 9.00 | 3.60 | 11 | 0.400 | 0.3200 |
| 11.00 | 3.75 | N | 0.340 | 0.2720 |
| 15.50 | 3.90 | 18 | 0.251 | 0.2008 |
| 20.50 | 4.00 | н | 0.195 | 0.1560 |
| 27.00 | 4.00 | of . | 0.149 | 0.1192 |
| 31.00 | 4.20 | 10 | 0.135 | 0.1080 |








| 1. | и1. | R.P.M. | R. | R/ ". |
|------|------|--------|-------|--------|
| 30.0 | 2.75 | 990. | 0.916 | 0.7328 |
| 11 | 2.90 | 1045. | 0.966 | 0.7728 |
| (II) | 3.00 | 1156. | 0.100 | 0.0800 |
| (0) | 3.40 | 1200. | 0.113 | 0.0904 |
| 18 | 3.90 | 1275. | 0.130 | 0.1040 |
| 29.0 | 4.20 | 1350. | 0.144 | 0.1152 |
| ti . | 5.00 | 1425. | 0.172 | 0.1376 |
| 13 | | | | |


#18.

| Ι. | к1. | R.P.M. | R. | R/ ". |
|-------|-------|--------|-------|---------|
| 3,5 | 1.90 | 900. | 0.542 | 0.4336 |
| 5.5 | 2.25 | ** | 0.409 | 0.3672 |
| 8. 25 | 2.75 | 17 | 0/333 | 0.2554 |
| 13.50 | 3. 25 | 40 | 0.241 | 0.1928 |
| 16.50 | 3, 50 | 40 | 0.212 | 0.1696 |
| 22.50 | 3.70 | 01 | 0.164 | .0.1312 |
| 26.50 | 3.80 | ** | 0.143 | 0.1144 |
| 29.00 | 4.00 | 98 | 0.138 | 0.1104 |












| 1. | nl. | R.P.M. | R. | R/- ". |
|-------|-------|--------|--------|--------|
| 6.00 | 1.20 | 1000. | 0.200 | 0.1000 |
| 7.5 | 1.30 | 19 | 0.173 | 0.0886 |
| 10.25 | 1.50 | 17 | 0.146 | 0.0730 |
| 12.00 | 1.60 | 11 | 0.133 | 0.0515 |
| 15.00 | 1.80 | d | 0.120 | 0.0600 |
| 17.00 | 1.75 | 19 | 0.103 | 0.0515 |
| 20.50 | 2.00 | 11 | 0.0975 | 0.0487 |
| 21.50 | 2.00 | 10 | 0.093 | 0.0460 |
| 25.50 | 2. 20 | 69 | 0.087 | 0.0436 |
| 26.50 | 2. 20 | 11 | 0.083 | 0.0416 |
| 27.50 | 2.30 | 17 | 0.084 | 0.0420 |
| 30.00 | 2.50 | -11 | 0.083 | 0.0415 |


#20.

| Ι. | RI. | R.P.M. | R. | R/ ". |
|--------|-------|--------|-------|--------|
| 12.00 | 1.75 | 1130. | 0.145 | 0.0720 |
| 15.00 | 1.90 | tl. | 0.134 | 0.0670 |
| 19.00 | 1.70 | a) | 0.090 | 0.0450 |
| 21.50 | 2.10 | 0 | 0.097 | 0.0480 |
| 22.50 | 2. 20 | 11 | 0.097 | 0.0480 |
| 26, 25 | 2.30 | e | 0.080 | 0.0400 |












| Ι. | nl. | RPP.M. | R. | R/ ". |
|--------------|------|--------|-------|-------|
| 5 . U | 1.2 | 1260. | 0.240 | 0.120 |
| 11.0 | 1.7 | 1f | 0.154 | 0.077 |
| 18.0 | 2. 2 | d | 0.122 | 0.061 |
| 20.0 | 2.2 | if | 0.110 | 0.055 |
| 23.5 | 2.5 | п | 0.106 | 0.053 |
| 28.5 | 2.7 | 19 | 095 | 0.047 |
| 30.5 | 2.7 | ii. | 0.088 | 0.044 |
| | | | | |


#22.

| Ι. | KI. | R.P.M. | R. | BR/ ". |
|-------|-----|--------|-------|--------|
| 5.00 | 2.0 | 1400. | 0.400 | 0.200 |
| 10.5 | 2.3 | 10 | 0.219 | 0.109 |
| 17.75 | 2.8 | 18 | 0.154 | 0.077 |
| 19.50 | 2.9 | 48 | 0.148 | 0.074 |
| 21.50 | 3.0 | 99 | 0.139 | 0.069 |
| 26.50 | 3.1 | 49 | 0.117 | 0.058 |
| 31.50 | 3.2 | ** | 0.101 | 0.050 |













| 1. | KI. | R. | R/ ". | R.P.M. |
|------|-------|-------|--------|--------|
| 29.5 | 2, 25 | 0.079 | 0.039 | 720. |
| ȣ | 2.30 | 0.078 | 0.039 | 765. |
| 11 | 2.40 | 0.081 | 0.040 | 810. |
| 18 | 2.40 | 0.081 | 0.040 | 855. |
| ** | 2.75 | 0.093 | 0.046 | 900. |
| 69 | 2.90 | 0.098 | 0.049 | 945. |
| et | 2.90 | 0.098 | 0.049 | 990. |
| 13 | 3.10 | 0.105 | 0.052 | 1035. |
| 41 | 3. 25 | 0.110 | 0.055 | 1080. |
| | | | | |
| | | #24 | 1. | |
| I. | R.I. | R. | R/ ". | R.P.M. |
| 17.5 | 1.5 | 0.085 | 0.0425 | 720. |

| Ι. | K.I. | R. | R/ ". | R.P.M. |
|------|------|-------|--------|--------|
| 17.5 | 1.5 | 0.085 | 0.0425 | 720. |
| 76 | 1.7 | 0.097 | 0.0485 | 765. |
| 11 | 1.9 | 0.109 | 0.0545 | 810. |
| *1 | 2.1 | 0.120 | 0.0600 | 855. |
| 11 | 2.2 | 0.125 | 0.0625 | 900. |
| ., | 3.0 | 0.200 | 0.1000 | 945. |
| 4.6 | 2.7 | 0.155 | 0.0775 | 990. |
| ., | 2.9 | 0.160 | 0.0800 | 1035. |
| ** | 3.0 | 0.200 | 0.1000 | 1080. |














| 1. | к1. | R. | R/ ". | R. P. M. |
|----------------|------------------------------|----------------------------------|----------------------------------|------------------------------|
| 10.0 | 1.1 | 0.110 | 0.055 | 720. |
| ď | 1.6 | 0.160 | 0.080 | 765. |
| 10 | 1.8 | 0.180 | 0.090 | 810. |
| ū | 2.4 | 0.240 | 0.120 | 885. |
| 16 | 2.7 | 0.270 | 0.135 | 900. |
| 16 | 3.5 | 0.350 | 0.175n | 945. |
| 9.5 | 3.0 | 0.136 | 0.158 | 990. |
| 18 | 2.75 | 0.248 | 0.124 | 1035 |
| 19 | 2. 20 | 0.226 | 0.113 | 1080. |
| | | | | |
| | | #20 | ō . | |
| 1. | KI. | R. | R/ ". | R.P.M. |
| 9,5 | 1.20 | 0.126 | 0.062 | 720. |
| 0 | | | | |
| | 1.70 | 0.180 | 0.090 | 765. |
| 18 | 1.70 | 0.180 0.248 | 0.090 | 765. 810. |
| 58 18 | , | | | |
| | 1.75 | 0.248 | 0.124 | 810. |
| 10 | 1.75 2.00 | 0.248 | 0.124 | 810. 855. |
| 13 | 1.75 2.00 2.30 | 0.248 0.210 0.242 | 0.124 0.105 0.121 | 810. 855. 900. |
| 13 14 14 | 1.75 2.00 2.30 3.00 | 0.248 0.210 0.242 0.316 | 0.124 0.105 0.121 0.158 | 810. 855. 900. 945. |











#27.

| - | | 9 | 77.6% |
|------|------|-----|--------|
| - 12 | 2211 | sh | #3. |
| D | 111 | DIT | 7/ 0 . |


| Tens. | R.P.M. | Scale. | K. |
|-------|--------|--------------|-------|
| 30. | 800. | 16.0 | 1.41 |
| 88 | 900. | 15.0 | 1.32 |
| 27 | 1020. | 14.0 | 1. 32 |
| +9 | 1150. | 13.5 | 1.23 |
| # | 1275. | 13.0 | 1.23 |
| 19 | 1425. | 12.5 | 1.19 |
| +1 | 1610. | 12.0 | 1.14 |
| • | | #28 . | |
| | | | |

Brush #2.


| | - | "," | |
|-------|--------|--------|------|
| Tens. | R.P.M. | Scale. | K. |
| 40. | 800. | 18.0 | 1.21 |
| ** | 900. | 17.5 | 1.17 |
| # | 1000. | 17.0 | 1.14 |
| 17 | 1200. | 16.0 | 1.08 |
| 09 | 1300. | 14.0 | 0.94 |
| ** . | 1500. | 12.0 | 0.81 |
| | | #29. | |
| 40. | 1300. | 16.6 | 1.11 |

(Mote) Brush number two was inclined about ten degrees against direction of rotation of commutator.











It will be noted in the foregoing curves and data that the contact resistance is not a linear function of either the speed or current density. In the case of the speed contact resistance curves this may be explained from the fact that the impulses which are given by the passing of each segment, occur oftener and are of shorter duration as the frequency of commutation increases. As these impulses occur oftener the spring neets with a greater resistance in restoring the pressure between the brush and the commutator to its origonal value and, as the natural period of the spring is many times the period of the impulses, there is not the same pressure exerted normally to the commutator by the brush as in the case where the frequency of commutation is lower.

Arguing from this stand-point there will be a point at which



the tension of the spring will be balanced against the impulses and no decrease in the pressure of the brush on the commutator will be noticed. This point is shown in curve number one. It was found on others when the speed was carried high enough. In cases where the commutator ran against the slant of the brushes this point occured at speeds much above those used in modern machinery.

The point where a given increment of speed has a minimum effect in increasing the resistance is met at lower speeds where the brush slants in the direction rather than where the slant is opposed to the direction of rotation. This is because in the first case practically all the shock given the brush is taken up in forcing the brush away from the surface of the commutator while in the second case there is a component forcing the brush in the direction of rotation which tends to maintain the pressure between the brush and the commutator. This component also increases the frictional resistance given to the relative motion of the brush and holder which gives less displacment and is consequently more quickly overcome by the spring.

The fore going may perhaps be made more clear by consideration of figures A and B.




The friction between brush and commutator in both cases exerts a force on the brush in the direction indicated by P., which in case one will tend to make the brush bear harder on the commutator. In case two the pressure will be somewhat releived. A curve for the condition one is shown on curve sheet number two and in case two is shown on curve sheet number one. The only difference in conditions under which these two curves were made was that of the brush slant.

From these considerations it will be seen that a brush having slant in the direction of rotation is to be prefered in cases where the peripheral speed of the commutator is low. At high peripheral speeds there is but little choice between slant forward and slant backward.

If the slant be opposed a brush holder must be used in which the brush is free to moveand the holder perfectly rigid or the pressure may become so great as to drag the holder around its stud and damage the commutator. When the slant is in the direction of rotation a holder that moves with the brush is to be prefered, for, the brush is then held rigid in two directions and is not so free to "chatter".


The pressure that is added to that of the spring by friction between the brush and commutator makes an error in the coefficient of friction as determined when the machine is running.



The coefficient is calculated with regard to the magnitude of the tension in the spring which is much lower than the actual pressure between the brushes and the commutator. This gives a coefficient that is high in value and differing for different slants against rotation but nearly constant and correct if the brush be slanted in the opposite direction.

These coefficients were found by balancing the torque on the holder by means of a spring balance and the forces of friction calculated by taking moments about the center of the shaft of the machine.

The sets of data numbered twenty seven and twenty eight were made with the brush perpendicular to a tangent of the commutator and show that the coefficient of friction, in proportion to increase of speed. This is what may be expected if the hypothesis advanced in regard to resistance increase is true. This coefficient as determined with the brush in this position relative to the commutator will be the true coefficient. That in data number 29 was made when the brush was inclined against the direction of rotation and shows conclusively that, in the case where the brush has this position, there is a greater pressure between the brush and the commutator than is given by the spring alone. Calculating backward from the coefficient of fric tion it is found that the increase of pressure is about 15%. The incline of the brush was approximately ten degrees.



The curves made to show the relation between contact resistance an' current density are somewhat surprising. At first it was believed that the decrease of resistance might be due to the temperature changes but after a careful repitition the curves were found to repeat themselves. Constant temperature was obtained in this case by allowing the brush to carry maximum current at all times except when readings were made. There readings were made as quickly as possible after the current was reduced in order to miniminize any changes of temperature by radiation.

The fall in resistance is greater than could possibly be attributed to the change of resistance in the carbons within the temperature range that was maintained.

This fall in potential might possibly be attributed to an electrolytic action in the infinitessimal air-gap that exists between the carbon and the commutator. In this case we might make the assumption that finely divided carbon forms the conducting medium in the gap and that more is carried from the brush at high currnet densities than at lower densities.

Besides the above given theory there is one other that might be advanced, namely, that there may possibly be a rearrangment of the molecular or atomic construction of the brush. This seems more probable than the former.



If the first explaination be the true one a different resistance might be expected at the positive brush than at the negative one, for a given set of conditions. The potential drop for a constant given current might be a little lower for the positive than that at the negative brush or it might be higher. This will depend on whether or not the "ionizing", as we may term it, of the air gap requires less or more energy than that to overcome the pure resistance of the thin layer of air.

To find if the above mentioned descrepancy it would be of advantage, if not necessity, to use a smooth surface as that of a slip ring in place of a commutator as the difference would be so small that the oscilation of the brush might hide it. to get the same conditions when measuring between a negative brush and the ring as when measuring for the positive it would be well to cause the positive brush to become a negative one by simply reversing the current. One terminal of the voltmeter should be attatched to the brush and the other to a small metalic strip making a rubbing contact on the surface of the ring. If this method give a consistant difference in the potential drop between a brush and commutator, under constant conditions, when used as a positive and negative electrode we may be justified in saying that there is an electrolytic action




present. If there is no difference we would not be justified in saying that there was no electrolytic reaction as it might be balanced by potential drop at the negative brush, or too small to detect.

In case no difference in the resistance is found when a brush is used as a positive and when used as a negative the question as to whether the change of resistance with current density is due to electrolysis or a rearrangment of atoms is still open.

The curves on sheet number five, made under similar conditions except as to temperature, show a convergence that indicates a limiting minimum value to the resistance. This fact might bear out either supposition that has been made. This change is much greater for a given increment of current at low current densities.

In all the curves plotted for this experiment the resistance for both positive brushes and negative brushes are used as that is the condition found in the actual operation of Direct Current Machinery.








The injury caused by sparking is due to an excessive current in the coil that, during commutation is short circuited by the brush. The object of this experiment is to find the magnitude of this current that flows during short circuit and how is rises at different stages of commutation, how it is changed by change of load, voltage, speed, position of brushes, ect. Also to show what shape it should follow in order that good commutation would result. How can this shape be obtained?

The scheme for accomplishing this is to measure the fall of potential over one of the end connectors with a sensative galvonometer and a low reading potentiometer.

Slip rings were mounted on the shoulder of the commutator and corrected to two points on an end connector, one point being close to the armature and the other at the commutator riser. By using a contact maker the fall of potential over this may be taken for the various positions of the armature coil.

SCHEME: -



APPARATUS: -

Leeds Northrupp Potentiometer.

Weston Reflecting Galvonometer.

Contact-maker.


Standard Cadmium Cell.

Westinghouse Generator. 15 K. W.-115 Volts.-120. Amp. DISCUSSION:-

The sparking of a generator is caused by a large current in a coil which is necessarily short circuited during the period of cornutation. The magnitude of this current depends on the E. M. F. acting in that coil and the resistance of the coil, end connectors, brush, and commutator segments.

The E. M. F. induced in the coil will depend on the speed of the armantre and on the strength of the field it is passing through at short circuit. The field that it is cutting is not only the field of the machine as there is a field of self-induction and a field of mutual -induction as the current in the preceeding coil rises after reversal and as the succeeding coil current falls off before reversal.

The current in the preceeding coil has an effect that, in lap windings is added to that of the following coil. This total may or may not oppose the E. M. F. generated by any of the machine field that may be threading the short circuited coil,



depending on whether the brushes have lag or lead. The E.M.F. of self-induction always tending to prevent a great change of current in any case. In the ideal case the change of current in the short circuited coil will be gradual and nearly a straight line as the current falls to zero from one direction and increases from zero in the other.

This may be realized at slow speeds as the current change is comparatively slow and the inductions, self and mutual, are small. If the coil now be located in a neutral part of the machines field there will be but a small current in the short circuited coil and the current distribution will be governed by Kirchoff's laws and if the current be plotted as a function of time the curve will be much the same as shown in figure.

The greater the reactance of the coil the more nearly a straight line the transition will be. In this case the current density is uniform over all the face of the brush, there

This result ray be accomplished at high speed if the E. M. F. of self-induction and the E. M. F. caused by the machine field are balanced. If the transition be a straight line the E. M. F. of self-induction is constant and for a set of given conditions may be balanced by giving the brushes the right

is no sparking and the heating of the armature is a minimum.



amount of lead as is done in practice. This however requires a different position for each change of load to secure the ideal case, though in practice one setting, that for full load or rather maximum load the machine is to carry, usuallt gives sparkless commutation though the armature heats considerably. This may be practically neutralized by a resistance in the contact or end connectors, preferably the former, that will give sufficient ohmic drop to keep the current in the short circuited coil within low limits.

On account of mechanical disturbances of the galvonometer it has been as yet impossible to obtain data on this point.













